

services available please contact: For further details of Ottfur Release Units and the support


Cair Aviation Limited Steephill House Furnace Wood Felbridge Felcot Road


West Sussex

RH19 2PX England Tel:+44 (0)1342 712684 Fax: +44 (0)1342 717082

e-mail colin@cairaviation.co.uk

www.cairaviation.co.uk check our website on





IMPORTANT

Keep the LOG BOOK with the glider documents for use when checking the Ottfur Release Unit during C of A's etc. Should it become necessary to return the unit to the manufacturer PLEASE Include this LOG BOOK

OTTFUR QUICK RELEASE UNITS

GENERAL INFORMATION, CARE AND MAINTENANCE

Each new and reconditioned unit is tested prior to delivery and is accompanied by a Test and Data Sheet and Release Certificate with a Parts and Labour Warranty for a period of 6 months for reconditioned units and 12 months for new units.

NOTE: The test carried out prior to delivery may cause some marking to the book beak and ring carriage.


In the interest of maintaining the highest level of quality control it is recommended that unserviceable units are always returned for repair and/or reconditioning. Cair Aviation Limited, who own the design and manufacturing rights of the OTTFUR release, operate a return service on standard units.

The Calr Aviation service policy dictates that ready for use standard OTTFUR units are available from off the shelf stock and in consequence, with the exception of Spring Change Kits, sub-assembly spares are not available.

2. MK1 OTTFUR ON100 SERIES Q.R. UNITS

These units are the standard OTTFUR Quick Release Units.

As described above a full support service is available for these units and to avoid any confusion, which may result from the various configurations in service these have been rationalised into FIVE common types:



3.1 CARE AND MAINTENANCE

To ensure a long and trouble free service life it is important that the units are regularly serviced and the following notes are offered as guidance for routine servicing and maintenance.

4.1 SERVICING

Servicing is limited to cleaning and lubrication on a regular basis, the periodicity depending on usage and environment ideally this period should not exceed six months.

As most units, of necessity, are positioned such that they can collect the maximum amount of mud and dirt the use of grease as a means of lubrication should be avoided.

Units should be thoroughly cleaned with petrol or paraffin, blown out and dried with an air gun and then lubricated with an approved aviation lubricant such as Shell Aviation Fluid 3 or its equivalent.

4.2 INSPECTION

The following inspections and checks should be carried out on an annual basis:

- Remove Q.R. unit(s) from the glider
- Clean and dry the unit thoroughly

=====

- Where applicable inspect the back release ring carriage for excessive wear, especially on the forward inside edge of the ring.
- Check the throat of the Hook for distortion and wear.

Z

5

Check the Casing at the throat for distortion and wear of the casing side plates.

- چ bearings for war by rocking them laterally. Check the Hook, Ring Carriage and Release Lever
- S check tighten both the 1/2 inch BSF pivot nuts. and signs of impending failure, or fracture and Inspect both springs for distortion, misalignment
- ¥ Carry out a no load pull check on the Release

 $(5.5 lbs \pm 2.2 lbs)$ As a guide this figure should be 2.5daN ± 1.0daN

(3.3lbs) the Lever Spring should be replaced. If the pull force required is leass than 1.5daN

a lack of lubrication. If further lubrication fails to improve this figure the unit should be rejected A pull force in excess of 3.5daN (7.7lbs) may indicate

movement). Free fore and aft movement should not (Lateral movement) or linkage wear (Fore and Aft Free movement of the Beak indicates bush wear

X inside edge of the Ring Carriage. mechanism by applying a pull force to the rear Carry out a no load pull check on the Back Release

should be changed Release is less than 4.5daN (10lbs) the Back Release Spring As a guide this figure should be $5.5 \text{daN} \pm 1.0 \text{daN}$ (12lbs \pm 2lbs). If the force required operate the Back

a lack of lubrication. If further lubrication fails to improve A pulll force of more than 6.5daN (14.5lbs) may indicate the test figure the unit should be replaced

> × high pull forces the unit should be returned for unit exhibits a combination of excessive wear and found to be low, replacing the springs with new bush wear acceptable but pull force figures are Where the general condition of the unit is good and items will usually provide a solution. However if the

¥. re-install in the glider. unit with Shell Aviation Fluid 3 or its equivalent and above and any associated servicing, lubricate the On satisfactory completion of the checks listed

× Carry out insitu functional check, i.e. Free Drop, Forward and Back Release.

RECOMMENDATIONS

Ç

- Avoid the use of grease as a lubricant
- Avoid acute sideways angles when ground towing

ت و و و ح

- Avoid applying snatch loads when ground towing Invest in a pair of proper cable rings for ground
- Bulko
- ٤ \$ better than not enough If one Spring needs changing - change both - it Clean and lubricate regularly - more often is much
- saves time.
- က <u>က</u> THE OTTFUR MK1 ON SERVES RELEVANT PART NUMBERS

Type A - 0M102 Type B - 0M103

Type C - OM104 Type D - OM105

Type E - OM106

SPRING REPLACEMENT

7.1 BACK RELEASE SPRING (OM123/13)

Fitting this spring requires some form of compression tool to align the spring ends with the locating split pins. It is also necessary to partially withdraw the hook/ring carriage pivot bolt to facilitate fitting.

7.2 RELEASE LEVER SPRING (OM123/14)

These springs are delivered as standard for the TYPE 8 (OM103) release units. For other units it will be necessary to bend the spring legs to the correct orientation for the type of release to which it is being fitted. Fitting is achieved by removing the lever pivot bolt and withdrawing the lever from the casing. It is not necessary to discorrect the lever from the link. Where applicable remove the 2BA spring retention bolt, push the spring legs back with a slim screwdriver and replace the 2BA bolt.

NB: The pivot bolt nuts should be tightened to 70-90lbs ins.

7.3 SPRING/BUSH REPLACEMENT KITS.

Spring/Bush change kits are available from Cair Aviation Ltd.

Part No. OM100SK suffixed by the Type letter

Note: T49 Capstan BR Springs are left handed and the RL Spring is also used in the Canopy catch.

7.4 COMPATIBILITY.

All OM Units are compatible with Tost Rings (LN65901).

THE MANUFACTURERS RESERVE THE RIGHT TO ALTER THE SPECIFICATIONS AT ANY TIME, AS THEY HAVE A POLICY OF CONTINUOUS DEVELOPMENT.

က

NITIAL FUNCTIONAL TEST RESULTS

TYPE: (MGD) SERIAL NO. REPORT No. 29

						S				i i
	OM100PDT	LEST		o ol	<i>y</i> 33	SECOCK (viii)	PELEASE LEVER		Î	iú
	OPDT	TESTED TO		थ्य	day				14/02/06	nan _e
_		andrographic data per la com-	LOAD TIEST	0,6	7.	BREAKOUT (ix):	BACK RELEASE	NO LOAD TESTS	06	
	30 e		EST	Charles		NA UK	ELEASE	TEST		Sici
	daN	20 45		BS	S N	يغر ويداد مداد ويداد ويد		(A)	A	SIGNATURE
	8.0	© 20 daN (45lbs)		16.0	7-3	FULL TRAVEL:	BACK RELEASE			>
	5	18		bs	<u>S</u>	<u> </u>	ASE		TO ALL MAN	BOX SEALON
		C								-

WARNING

OM 100 UNITS DO NOT HAVE AN ADJUSTER.

Each unit set up is physically unique and units should <u>NEVER</u> be made up from a mix of sevicable components from a number of other units.

ON COMPLETION OF SPRING CHANGE ALWAYS RE-ASSEMBLE 3/16" SPACER TUBING IN THEIR ORIGINAL POSITIONS.

OTTFUR OR UNIT RELEASE CERTIFICATE No. CAIR AVIATION LTD, CRAWLEY, RH10 3PA, ENGLAND AUTHORITY BRITISH GLIDING ASSOCIATION

TIEM PART No. SERIAL No. ELIGIBILITY
OTTFUR QR (こらとんの) (と |) フタフス BGA VARIOUS

NEW REFURBISHED BCAR(E) JAR 22 LIFE USED

Certified that the above QR Unit has been Manufactured/Refurbished and Tested in compliance with the Regulations as implicated above and prepared in accordance with the British Gliding Association's Technical Procedures Manual as amended at the date of this Certificate and is considered to be ready for release to service in installation compatible gliders registered with the British Gliding Association.

Signature: Name: Date: 14 02 06

Notes:

- Where the end user is subject to the regulations of an Airworthiness Authority other than the British Gliding Association it is essential that the end user ensures that his/her Airworthiness Authority accepts the QR Units certification under the British Gliding Association's regulations.
- This certificate does not constitute installation certification, in all cases, including BGA registered gliders, the installation must be recorded and certified in the Glider Log Book.

REFURBISHMENT FUNCTIONAL TEST RESULTS

TYPE:	SERIAL No.	REPORT No:
DATE:	SIG	SIGNATURE
	NO LOAD TESTS	0
RELEASE LEVER UNLOCK (viii)	BACK RELEASE BREAKOUT (IX):	BACK RELEASE FULL TRAVEL:
daN		Can
LOAD TEST		lbs lbs
OT CTTS		NULYONS
SK7/38 &	(B)	@ 20 Dan (45lbs)
OMIOPDI		

WARNING

OM 100 UNITS DO NOT HAVE AN ADJUSTER.

Each unit set up is physically unique and units should <u>NEVER</u> be made up from a mix of sevicable components from a number of other units.

ON COMPLETION OF SPRING CHANGE ALWAYS RE-ASSEMBLE 3/16" SPACER TUBING IN THEIR ORIGINAL POSITIONS.

ထ

delete as necessary"

OTTFUR OR UNIT RELEASE CERTIFICATE \$

BGA VARIOUS		•	OTTFUR OR
AUTIGIOTE	SERIAL No.	PART No.	TES
		ŕ	
NOILVE	BRITISH GLIDING ASSOCIATION	BRITISH	AUTHORITY
E L	CAIR AVIATION LTD, CRAWLEY, RH10 3PA. ENGLAND	LD, CRASS	CAIR AVIATION

	Š	
•	*REFURBISHED	
	*BCAR(E)	
1	*JAR 22	
	USED	

Certified that the above QR Unit has been Manufactured/Refurbished and Tested in compliance with the Regulations as indicated above and prepared in accordance with the British Gliding Association's Technical Procedures Manual as amended at the date of this Certificate and is considered to be ready for release to service in installation compatible gliders registered with the British Gliding Association.

Signature:	Name:
BGA insp. No.	Date:

Notes:

- Where the end user is subject to the regulations of an Airworthiness Authority other than the British Gliding Association it is essential that the end user ensures that his/her Airworthiness Authority accepts the QR Units certification under the British Gliding Association's regulations.
- 'n This certificate does not constitute installation certification, in all cases, including BGA registered gliders, the installation must be recorded and certified in the Glider Log Book.

Ö

SERVICE RECORDS

		Tellinasinismuse, n. n.p. d.n. der den Vistuagenzess admytess	t somme på de kantan som men på de de de kantal er gen samt bet det en på de de kantal som en se se se se se s	Фимбен о част драбийской кот дого составления, ег _{ан} ена		· \(\)
-				en e	•	102/2006
مناسقة فينجرون فالمناس)					Resistance
,			•			THANOAS ME

[&]quot;delete as necessary

NOTES SPECIFIC TO THIS UNIT:

BOTH CASING AND OROXATING LOVER
HANG BOOM MEDITIED TO SOIT
INSTAULTICEN IN SKYLAKK 4 BRANG.
THE STANDARD OM 106E UNIT
IS NOT INTERCOMANGEABLE GOSENOOF
WITH THIS UNIT.